



Quick Start Guide



Committed to Excellence. Dedicated to Quality. Certified to ISO 9001:2008 in Manufacturing Centers Worldwide.
©2017 Datacolor Inc. Datacolor and other Datacolor product trademarks are the property of Datacolor Inc.

1. USB Instrument Cable Connection



Connect USB Cable

Connect to Computer

2. Power Cord Connection



Connect Power Cord

Connect to Outlet

3. Power instrument. Locate black trap, white tile and green tile in accessories drawer. Launch a Datacolor program, and calibrate* the instrument.



Power Switch



Calibration Accessories

Part No. 019-400020, Rev B

* See User's Guide on USB Memory Stick for detailed instructions.